

Location	Specific	Issue	Addressed
Art Annex	Art Classroom	temperature needs adjusting room is warm	☒
Art Annex	Art Classroom	ceiling tile stained	☒
Art Annex	exterior	walk off matts need cleaning	☒
Art Annex	exterior north	black mold on concrete under cantaliever	☒
Art Annex	exterior north	black mold on window casings	☒
Art Annex	exterior south	some mold at roof/copper interface	☒
Art Annex	exterior west	screen under cantaliever falling apart	☒
Arts Center	exterior	incilation exposed to outside	☐
Arts Center	exterior	paint chipping on building	☐
Arts Center	exterior	old vents covered by garbage bag stuffed with incilation exposed to elements	☐
Arts Center	exterior	crusty fungus looking material on exterior side of building	☐
Arts Center	exterior	foundation cracks with rebarb popping out	☐
Arts Center	exterior	gutters growing vegetation and need cleaning	☒
Arts Center	old photo lab	chemicals in the sink	☐
Arts Center	piano lab	vent falling from ceiling	☐
Arts Center	stage right wing	can see through brick to the outside	☐
Field House	exterior north	poison ivy growing on emergency door	☒
Field House	exterior west	moss on gas source	☒
Field House	exterior west	broken glass	☐
Field House	exterior west	growth on HVAC system	☐
Field House	gym	mold at expossed paddings (x3)	☒
Field House	gym	insulation falling	☐
Field House	gym	no air return?	☒
Field House	lobby	mold at vent	☒
Field House	mechanical	gas furnace draining water on floor	☒
Field House	mechanical	broken tiles	☒
Field House	mechanical	cobwebs	☒
International House		104 mold in ceiling vent	☐
International House		104 falling paint	☐
International House		104 black mold on ceiling	☒
International House		104 puckering paint in brick	☐

International House	201	right conrer (SW) mold on ceiling	☐
International House	202	exterior wall puckering paint	☐
International House	1st floor entry	smell of must/mold/mildew	☐
International House	2nd commons	west wall puckering paint	☐
International House	bathroom 1st	paint ceiling falling	☐
International House	exterior east	mold on soffet	☐
International House	exterior north	black mold all along crown	☐
International House	exterior north	moss covering asphaul shingle stair cover	☐
International House	exterior north	weeds growing at foundation	☐
International House	exterior north	black mold on wood roof	☐
International House	exterior south	lichens on wood roof	☐
International House	exterior south	mechanical room doesn't lock	☐
International House	exterior west	lichens all over brick	☐
International House	RA2	bathroom ceiling water damage, mold and paint falling	☐
International House	stairwell 2nd fl	very strong odor	☐
International House	stairwell 2nd fl	black mold covering ceiling, water damage	☐
International House	stairwell 2nd fl	puckering paint in brick	☐
Library	bathroom	ceiling tiles stained	☒
Library	exterior east	leaves	☒
Library	exterior east	mold on crown	☒
Library	exterior south	tree encroaching on bilding	☐
Library	exterior west	plant growth in vent system through the grates	☒
Lower School	ceiling vents	through out the building need to be vacuum monthly	☐
Lower School	Counselors Office	ceiling tiles are stained and need to be changed	☒
Lower School	ELA classroom	ceiling tiles are stained and need to be changed	☒
Lower School	exterior	walk off matts need cleaning	☒
Lower School	exterior	water drain off from roof causing ground to cave in	☐
Lower School	exterior	Entrance to building ceiling needs to be repaired in the corner	☒
Lower School	room 131	ceiling tiles are stained and need to be changed	☒
Lower School	room 135	ceiling tiles are stained and need to be changed	☒
Lower School	Social Worker's Office	ceiling tiles are stained and need to be changed	☒

Upper School		102	brown tiles	☒
Upper School		105	ceiling water stained spot both rooms	☐
Upper School		107	tiles water stained spot	☒
Upper School		108	musty smell	☒
Upper School		109	smell of mold	☐
Upper School		111	mold on ceiling	☒
Upper School		111	water stained spots on tiles	☒
Upper School		113	water damage on tile	☐
Upper School		117	popped floor tiles (likely asbestos)	☒
Upper School		117	chipped paint	☒
Upper School		118	water stained tiles	☒
Upper School		118	cracked concrete	☐
Upper School		118	water stained tiles near stack fume hood	☐
Upper School		118	stains on exterior of waste pipe	☐
Upper School		119	brown tiles	☐
Upper School		119	water stained tiles	☐
Upper School		201	dirty vent return	☒
Upper School		202	water stained tiles	☒
Upper School		203	dirty vent return	☒
Upper School		205	water stained tiles major damage	☐
Upper School		205	bees, mouse droppings on windowsill	☒
Upper School	2nd floor		dirty hallway vent	☒
Upper School	boys 1st		smell of waste	☒
Upper School	boys 2nd		brown marks in ceiling,	☒
Upper School	boys 2nd		dirty air return	☐
Upper School	Boys room 2nd		water stained spot by sprinkler	☒
Upper School	exterior east		wasp nest on camera	☒
Upper School	exterior ewest		black mold on cracks in crown	☐
Upper School	exterior north		mold and algae growth vertically on cracks in crown	☐
Upper School	exterior south		bees nest, 2nd floor outside 205	☒
Upper School	exterior west		trees encroaching buliding (Japanese maple, bushes)	☐

Upper School	exterior west	hole near vents	☐
Upper School	greenhouse	cracked ceiling glass	☐
Upper School	lobby	consentation and intakes and vents	☒
Upper School	lobby	water stained spots on hallway tiles	☐