

Walkthrough Inspection Checklist

Name:	ACES Central Office IAQ Te	am	
School:	370 James Street, Suite 30	3, New Haven, CT	06513
Room or	Area: ALL	Date Completed:	11-7-2025
Signature	Todd A. Solli		

Inst		

- 1. Read the *IAQ*Backgrounder and the Background Information for this checklist.
- 2. Keep the
 Background
 Information and
 make a copy of
 the checklist for
 future reference.
- 3. Complete the Checklist.
 - Check the "yes,"
 "no," or
 "not applicable"
 box beside each
 item. (A "no"
 response
 requires further
 attention.)
 - Make comments in the "Notes" section as necessary.
- 4. Return the checklist portion of this document to the IAQ Coordinator.

1.	GROUND LEVEL	s N	No	N/A
1a.	Ensured that ventilation units operate properly	Ç		
1b.	Ensured there are no obstructions blocking air intakes	Ç		
1c.	Checked for nests and droppings near outdoor air intakes	Ç		
1d.	Determined that dumpsters are located away from doors, windows, and outdoor air intakes	a		
1e.	Checked potential sources of air contaminants near the building (chimneys, stacks, industrial plants, exhaust from nearby buildings)	3		
1f.	Ensured that vehicles avoid idling near outdoor air intakes			
_	Minimized pesticide application)		X
1h.	Ensured that there is proper drainage away from the building (including roof downspouts)	3		
1i.	Ensured that sprinklers spray away from the building and outdoor air intakes	ZÓ.		
1j.	Ensured that walk-off mats are used at exterior entrances and that	3	_	
13.	they are cleaned regularly	0		
2.	ROOF			
Wh	ile on the roof, consider inspecting the HVAC units (use the Ventilation Checkl	ist).		
2b.	Ensured that the roof is in good condition	X	_ _ _	
2d.	Ensured that exhaust fans operate properly (air flows out)	0		
2e.	Ensured that air intakes remain open, even at minimum setting	0		
	Checked for nests and droppings near outdoor air intakes)		
2g.	Ensured that air from plumbing stacks and exhaust outlets flows away from outdoor air intakes	נ		
3.	ATTIC			
3a.	Checked for evidence of roof and plumbing leaks	ב		X
	Checked for birds and animal nests			
4.	GENERAL CONSIDERATIONS			
4a.	Ensured that temperature and humidity are maintained within acceptable ranges	9		
4b.	Ensured that no obstructions exist in supply and exhaust vents			
	Checked for odors			
44	Checked for signs of mold and mildew growth	a		

4.	GENERAL CONSIDERATIONS (continued)	/ec	Nο	N/A
4e.	Checked for signs of water damage			
4f.				
4g.	Noted and reviewed all concerns from school occupants	, 🙀		
5.	BATHROOMS AND GENERAL PLUMBING			
	Ensured that bathrooms and restrooms have operating exhaust fans	X		
	Water is poured down floor drains once per week (approx. 1 quart of water)	X		
	Water is poured into sinks at least once per week (about 2 cups of water)	X		
	Toilets are flushed at least once per week	X		
6.	MAINTENANCE SUPPLIES			
6a.	Ensured that chemicals are used only with adequate ventilation and when			
	building is unoccupied	X		
6b.	Ensured that vents in chemical and trash storage areas are operating			
	properly	X		
6c.	Ensured that portable fuel containers are properly closed			X
6d.	Ensured that power equipment, like snowblowers and lawn mowers, have			
	been serviced and maintained according to manufacturers' guidelines			X
7.	COMBUSTION APPLIANCES			
7a.	Checked for combustion gas and fuel odors	X		
	Ensured that combustion appliances have flues or exhaust hoods			X
	Checked for leaks, disconnections, and deterioration			
	Ensured there is no soot on inside or outside of flue components			X
8.	OTHER			
Q ₀	Checked for peeling and flaking paint (if the building was built before			
oa.	1980, this could be a lead hazard)	X		
8h	Determined date of last radon test			
50.	Determined date of fast radon test	70.	J	•

NOTES

Last radon was in November of 2023 Space is a part of an office building. ACES occupies a section of the 3rd floor. Space was renovated "like new" in November of 2023